

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: 22 and 27	TOWNSHIP 1 South	RANGE 10 West
COUNTY: Tillamook		DATE: 2-17-09
CORNER DESIGNATION: The Quarter Corner Common to Sections 22 and 27, T. 1 S., R. 10 W., W.M.		(Please check one)
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input checked="" type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
		<input type="checkbox"/> Reset at surface
		<input type="checkbox"/> Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0053 Page 197 (GLO 1S10 Pg. 32) (1857), Book 2 Page 477 (1961), Rewitness #312 (1981), Map B-1302 (1988), Book 6 Page 349 Note #5 (1988), Tillamook County Survey Records.		
Found Monument(s) and Accessories (Condition & Source): Found a 3" brass cap in cement, leaning slightly on a sliding hill. The monument is stamped as shown hereon. Tied the monument directly using GPS established control. The Oregon North Zone State Plane in NAD 83/91 coordinate for the monument is N = 673386.588, E = 7330955.995 U.S. Survey Foot. Found 1 1/2" Iron Pipe lying next to the monument. Found a hat section post with a yellow metal location tag 2.0' west of the cap. (Book 2, Page 477) – Found (32" Hemlock stump), 5' tall, hollow with no marks, bears (S3° E 53.1'). (Book 2, Page 477) – Found Hemlock uproot (was 4"), bears (S 60 3/4° W 15.5'). (Book 2, Page 477) – Found root wad (was 34" Hemlock), bears (N 4 1/2° W 4.0'). () Indicates record information from Book 2, Page 477, Tillamook County Survey Records.		
Monument Set (Procedures and Description): Not applicable.	Sketch of Found Monument:	
New accessories set: Dug a shelf in the hillside for the monument to sit flush, plumbed the monument. Set 120 lbs. of concrete in a 12" cylinder around monument. Set a rock collar.		
New Bearing Trees set: 7" diameter Fir bears N 26° W 34.1', scribed, "1/4 S22 BT CS", tagged and painted. 10" diameter Fir bears S 69° E 50.2', scribed, "T1S R10W S27 BT", tagged and painted. All new bearing trees have a nail and aluminum washer marked, "Till. Co. Surveyor", in face of blaze, between the scribed B and T, and a yellow metal location tag affixed.		
Location & Comments: Corner is located approx. 400' west of gravel logging road #701.		
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141		SURVEYOR'S SEAL
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor		
Notes:		
Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor Michael R. Rice, L.S.I. 16723, Survey Technician		

