

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: SW Cor. 27	TOWNSHIP 3 North	RANGE 8 West
COUNTY: Tillamook		DATE: 5-05-09
CORNER DESIGNATION: The Section Corner common to 27, 28, 33 and 34.		(Please check one)
		<input checked="" type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0354 Page 93 - 94 (1891), Book 1 Page 193 (1954), Book 7 Page 126 & 126A (1992), Tillamook County Survey Records.		
Found Monument(s) and Accessories (Condition & Source): Found a 3" O.S.B.F. brass cap in good condition, in cement with a rock collar. The monument is stamped as shown hereon. Found a white cedar post with yellow O.S.B.F. tag, 1' SE of corner. Found a hat section post with tag North 1.5' from monument. (G.L.O.) – Did not find the (12" Hemlock bearing N 70° E 13 lks.). (G.L.O.) – Found a rotten Hemlock Stump (was 24" dia.), 4' tall, bearing (S 63° E 62 lks.). (G.L.O.) – Found rotten Hemlock Stump remains (was 18" dia.), bearing (S 60° W 29 lks.). (G.L.O.) – Did not find the (10" Hemlock bearing N 78° W 62 lks.). (Book 1, Page 193) – Found (54" Fir Stump), 10' tall, bearing (N 22° E 6.2'), scribed "T3N R8W S27 BT RE2311", with tag. (Book 1, Page 193) – Found a rotten Fir Stump (was 47"), 7' tall, bearing (N 15° W 21.9'), partial scribing visible. (Book 1, Page 193) – Found (48") Fir Stump, 3' tall, bearing (S 34° E 98.7'), scribed "T3N R8W S34 BT RE2311", with tag. (Book 1, Page 193) – Found (52" Fir Stump), 3' tall, bearing (S 46° W 63.6'), scribed "T3N R8W S33 BT RE2311", with tag. (Book 7, Page 126) – Found 17" (was 12") Alder on the south side of McPherson Creek Road, bearing (N 20° E 80'), tag. (Book 7, Page 126) – Did not find the 4" X 4" white post on the south side of McPherson Creek Road. (Book 7, Page 126) – Found 21" (was 14") Fir bearing (S 34° W 14.48'), with a healed over face and tag. (Book 7, Page 126) – Found 25" (was 17") Fir bearing (N 81° W 43.34'), with a healed over face and tag. () Indicates record information.		
Monument Set (Procedures and Description): Not applicable.	Sketch of Found Monument:	
New accessories set: N/A		
New Bearing Trees set: N/A		
Location & Comments: This corner is located approximately S 20° W 80', of McPherson Creek Road, (A.K.A. Lost Creek Road). To reach from the intersection of Cook Creek Road and the Upper Nehalem River Road at the CCC Bridge, go Southerly on Cook Creek Road 1.4 miles to the intersection of McPherson Creek Road turn left and follow main travelled road 7.4 miles to a yellow metal location poster on a 17" Alder on the right.		
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141		SURVEYOR'S SEAL
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor		<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;"> REGISTERED PROFESSIONAL LAND SURVEYOR </div> <div style="text-align: center; margin: 5px 0;"> <i>Joseph V. Jensen</i> </div> <div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;"> OREGON JANUARY 10, 2008 JOSEPH V. JENSEN 60067 </div>
Notes:		RENEWAL DATE: 08-30- 2011
Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor. Michael R. Rice, L.S.I. 16723, Survey Technician		

