

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: The Southeast Corner of Section 4	TOWNSHIP 2 South	RANGE 9 West	
COUNTY: Tillamook		DATE: 08-04-11	
CORNER DESIGNATION: The Section corner common to Sections 3, 4, 9, 10, Township 2 South, Range 9 West, W.M., Tillamook County, Oregon.		(Please check one)	
		<input checked="" type="checkbox"/> Condition Report Only	
		<input type="checkbox"/> Restoration	
		<input type="checkbox"/> Rewitness	
		<input type="checkbox"/> Unrecorded	
Previous Rewitnesses, Restorations and Surveys, etc.: BLM Field Notes Volume: OR-R0053 Page 345; Tillamook County GLO Book 2S09, Pages 10-11 (1857); Tillamook County Rewitness Card #357; Tillamook County Rewitness Book 1, Page 1; Tillamook County Rewitness Book 5, Page 119; Tillamook County Rewitness Book 6, Page 158; Hayes Fieldbook 'F' Page 96; Survey Map B-301, B-509, B-615, B-2506, B-3250, A-1681, A-3738, A-5141, A-3306, P-700, F-17-5, Tillamook County Survey Records.		<input type="checkbox"/> Reset at surface	
Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Tillamook County Surveyor Brass cap, up 1.0' from ground surface. Found monument is upright and in good condition and is inside a 10" tile with concrete in a swamp. The cap is stamped as shown hereon. Found a 30" diameter Alder tree with a 'Do not cut' tag attached at record position (was an 18" Alder tree bark scribed 'S3BTCS' bearing N.23°E 47.1'). Found an uprooted Spruce tree with tags attached (was a 24" Spruce tree scribed "S10BTCS" bearing S.21°45'E 20.3'). Found a 6" x 6" Air Base fence post leaning North (was a 6" x 6" Air Base fence post with cup tack in scribed circle 30" above ground bearing N.52°30'W 12.9'). Found an Alder tree approximately 12" in diameter with stretched scribing visible leaning severely to the North with a 'Do not cut' tag attached (was a 7" diameter Alder tree bark scribed "S9BTCS" bearing S.51°W 16.15'). Found a rotten 4" x 4" post with scribing visible (was a 4" x 4" x 48" post at 0.90' East).		<input type="checkbox"/> Referenced Out	
Reference monument location:		Sketch of Found Monument::	
<p style="color:red; font-weight:bold;">3/10/14 MARKER DISTURBED STRTND/RETIED</p> <p style="color:red; font-weight:bold;">151.61</p> <p>NOT TO SCALE</p>			
New accessories set: We set GPS established control to conventionally tie the corner monument. The two (2) control monuments (5/8" rebar with yellow plastic cap stamped "Tillamook Co. Random") are included as references to the found corner monument. The Oregon North Zone State Plane in NAD 83/91 grid coordinate position for the corner monument is N = 656120.692, E = 7359403.175, U.S. Feet. The Oregon North Zone State Plane in NAD 83/91 grid coordinate position for monument number 1 is N = 656028.430, E = 7359282.756, U.S. Feet. The Oregon North Zone State Plane in NAD 83/91 grid coordinate position for monument 2 is N = 655776.141, E = 7359389.597, U.S. Feet. This corner has been conventionally field tied twice with the results being averaged.			
New Bearing Trees Set: No new bearing trees set.			
Location & Comments: This corner is located approximately 80 feet West of a sharp curve in Brickyard County Road in a swampy area about 10' East of a North-South running fence at the Port of Tillamook Bay property.			
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141		SURVEYOR'S SEAL	
Party Chief: Joe Jensen, PLS 60067, Survey Supervisor, Deputy County Surveyor.		<div style="border: 1px solid black; padding: 5px; display: inline-block;"> REGISTERED PROFESSIONAL LAND SURVEYOR </div>	
Notes: Digital images were taken of the monument and the accessories.			
Witness: Danny R. McNutt, PLS 49230, Tillamook County Surveyor; Michael R. Rice, L.S.I. 16723, Survey Technician		<div style="border: 1px solid black; padding: 5px; display: inline-block;"> OREGON JANUARY 10, 2008 JOSEPH V. JENSEN 60067 </div>	
		RENEWAL DATE: 06-30-2013	

