



OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

BOOK 8 225

SECTION: 7 & 12		TOWNSHIP: 2 South	RANGE: 9/10 West
COUNTY: Tillamook		DATE: 4/17/2024	
CORNER DESIGNATION: The Meander Corner along the line common to Sections 7 and 12, Township 2 South, Range 9 and 10 West; Willamette Meridian		(Please check one)	
		X	Condition Report Only
			Restoration
			Rewitness
			Unrecorded
			Reset at surface
			Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc... BLM-OREGON Field Note Volume: OR-R0053 Page 0117.00 (1857), Rewitness Bk.4, Pg.36 (1929), Rewitness Bk.4, Pg.52 (1949), Rewitness Bk.4 Pg.101 (1964), Karl Foeste Field Note Bk. Sect. 1 Pg.8. (1973), B-700 (1975), Rewitness Card #365 (1978)			
History, condition, and sources In 1857 (BLM-Oregon Field Notes) a post was set for the Meander Corner along the line of Sections 7, T.2S, R9W and Section 12, T.2S, R.10W, and two bearing trees were established. In 1929 (Rewitness Bk.4 Pg.36) W.E Anderson established a new bearing tree. In 1949 (Rewitness Bk.4 Pg.52) W.E Anderson established three new accessories. In 1964 (Rewitness Bk.4 Pg.101) W.E Anderson establishes three new accessories. In 1973 (Karl E. Foeste Field Bk. Sect.1, Pg.8) Karl E. Foeste set a 5/8" iron bolt for the Meander Corner. In 1978 (Rewitness Card #365) Tillamook County Surveyor's Office replaced the 5/8" iron bolt with a 2" iron pipe with a 3" Tillamook County Brass Cap in tile with concrete stamped "MC S12 S7 2S10 2S9 RS 287 1978" and established three new accessories. In 2025 (MR Field Bk.18 Pg.13-14) the Tillamook County Surveyor's Office found a 3" Tillamook County Brass Cap in concrete stamped as shown hereon. Found accessories are listed below. Found: (Rewitness Bk.4 Pg.36: 30" dia. spruce S76°30'E 61.2') (Rewitness Card #365: fell in old channel of creek) Now Found in slough. Found: (Rewitness Bk.4 Pg.52: 30" dia. spruce N76°15'E 199.37') Now uprooted Found: (Rewitness Card #365: treated fence post S21°W 4.80') Now at Location with Metal Location Tag Found: (Rewitness Card #365: 86" hat section post East 17.30) Reset at East 13.65'			
New accessories set: The corner was tied directly using GPS established control in Oregon North Zone NAD 83/91 grid coordinates in US survey feet. Coordinates are provided here in WGS 84 Latitude and Longitude. Latitude: 45°25'07.49837" Longitude: -123°50'42.04016" No bearing trees available.		Pictures of Found Monuments: 	
Location: ±900' North of the intersection of Tillamook River Rd. and Ekloff Rd., ±28' East of centerline stripe.			
Tillamook County Surveyor office: 1510 3 rd Street Suite C, Tillamook, OR. 97141 Party Chief: Travis Porter, Tillamook County Survey Technician III Witnesses: Michael Rice P.L.S. 86926, Tillamook County Surveyor Kael Poklikuha, Tillamook County Survey Technician II Notes: Digital images taken of monument and accessories.		SURVEYOR'S SEAL REGISTERED PROFESSIONAL LAND SURVEYOR  OREGON DECEMBER 11, 2012 MICHAEL R. RICE 86926 RENEWAL 12-31-2026	

BOOK 8 225