OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT **Tillamook County Surveyor's Office** BOOK 8 230 **SECTION:** 29 & 32 TOWNSHIP: 2 North RANGE: 10 West **COUNTY:** Tillamook **DATE:** 6/27/25 **CORNER DESIGNATION:** (Please check one) Condition Report Only East 1/16 corner common to Section 29 and Section 32, Township 2 North, Restoration Range 10 West, W.M. Rewitness Unrecorded Reset at surface Referenced Out Previous Rewitnesses, Restorations and Surveys, etc. F 40-139 P-1196, B-4000, A-7279 Found Monument(s) and Accessories (Condition & Source): Found a 1-1/2" iron pipe set per F 40-139. Monument is approximately 0.8' below ground. An axle and three steel T posts are driven alongside. From the monument an 80"+ spruce stump, no markings visible, bears S15°E 20.0' to the face Monument Set (Procedures and Description): **Pictures of Found Monuments:** N/A New accessories set: N/A New Bearing Trees set: Distances to new bearing trees were measured to an aluminum nail at side center. 25" Alder bears N16°E 3.5', bark-scribed "E 1/16 S29 BT" 14" Alder bears S2°E 19.4', bark-scribed "E 1/16 S32 BT" **Location & Comments:** Firm / Agency SURVEYOR'S SEAL Address: Stuntzner Engineering & Forestry

2318-B Pacific Avenue Forest Grove, OR 97116

Party Chief: Corey Woodruff, PLS

Witnesses: John Hoshall

Notes:

REGISTERED **PROFESSIONAL** LAND SURVEYOR

OREGON
JULY 12, 2005
COREY WOODRUFF GONZ 62976

EXP. DATE 6/30/26

