# OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

## BOOK 8 232

<b>SECTION:</b> 9, 10, 15, & 16	TOWNSHIP: 2 South	R	RANGE: 10 West	
COUNTY: Tillamook		DATE: 5/12/2025		
CORNER DESIGNATION:  The Section Corner common to Sections 9, 10, 15, and 16 Township 2 South, Range 10 West, Willamette Meridian			(Please check one)	
			Condition Report Only	
			Restoration	
		X	Rewitness	
			Unrecorded	
			Reset at surface	
			Referenced Out	Y.F.

Previous Rewitnesses, Restorations and Surveys, etc...

BLM-OREGON Field Note Volume: OR-R0053 Page: 397 (1857), B-983 (1981)

#### History, condition, and sources:

In 1857 (BLM field notes) a post was set for the corner, and four bearing trees were established. In 1981 (B-983) Robert Olsen found a ½" iron pipe set by Hendrickson, Berg, Imstad, Everly, and Corbett from found original bearing trees. In 2025 Tillamook County Surveyor's office found a ½" iron pipe as shown hereon. Found accessories are listed below.

Found: broken stump stub N01°W 17.8' (B-983 broken off stub 5' high with no face or scribe marks N01°W 17.8')

Found: Debris pile S50°W 4.6' (B-983 rotting stump with old face evident but no scribing S50°W 4.6')

Found: badly rotted stump S20°E 29.3' (B-983 stump with nail in face on root S20°E 29.3'

#### New accessories set:

The monument was tied directly using GPS established control in Oregon North Zone NAD 83/91 grid coordinates in US Survey feet. Coordinates provided hereon are given in WGS 84 Latitude and Longitude.

Latitude: 45°24'22.46256" Longitude: -123°54'26.78972"

96" galvanized hat section post with yellow metal location tag South 1.0'

No new bearing trees suitable in the area.

### **Pictures of Found Monuments:**



Location: ±450' East of forest service Rd. # 100

Tillamook County Surveyor office: 1510 3rd Street Suite C, Tillamook, OR. 97141

Party Chief: Travis Porter, Tillamook County Survey Technician III

Witnesses: Michael Rice P.L.S. 86926, Tillamook County Surveyor Kael Poklikuha, Tillamook County Survey Technician II

Notes: Digital images taken of monument and accessories.

SURVEYOR'S SEAL

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
DECEMBER 11, 2012
MICHAEL R. RICE
86926

RENEWAL 12-31-2026

