OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: The 1/4 Corner of TOWNSHIP 2 South		RANGE 10 West			
Sec. 16 and 17 COUNTY: Tillamook		<u> </u>	DATE- 2 46 42		
CORNER DESIGNATION: The Quarter Corner common to Sections 16 and			6000		DATE: 2-16-12
17, T. 2 S., R. 10 W., W.M.					(Please check one) Condition Report Only
,	,				Restoration
				<u> </u>	Rewitness
					Unrecorded
					Reset at surface
					Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0053 Page 404 (GLO 2S10, page 19 1857), Rewitness AMA-10/33 same as Book 10 Page 119 (1895), Map A-372 (1949), Map A-774 (1958), Map A-782 (1958), Map A-1274 (1965), Map A-1933 (1970), Rewitness Book 3 Page 339 (1970), Map A-3467 (1978), Map A-4796 (1983), Map B-1820 (1994), Map A-6896 (1994), Partition Plat P-1011 (2011), Partition Plat P-1023 (2012), Tillamook County Survey Records. Found Monument(s) and Accessories (Condition & Source): Original Corner was set by GLO in 1857. In 1970, a dependent resurvey of Section 17, T. 2 S., R. 10 W., was performed by Charles G. Collard, PLS #376 on Map A-1933, where he found the					
Original NW Bearing Tree along with a 1 1/2" Iron Pipe. He then reset the monument as shown below. Found 2 1/2" dia. Crown Zellerbach Brass Cap, in concrete. Found Hat Section Post 1.0' Northwesterly of the monument. Found a white, painted cedar post lying down. Monument is stamped as shown hereon. The monument was then tied conventionally using GPS established control. The coordinates have been converted and are provided here in WGS 84, Latitude and Longitude. North = 45°23'56.49946", West= 123°55'40.26333" (GLO) – Did not find the (36" Hemlock bearing N 45° E 16 lks. [10.56']). (GLO) – Did not find the (30" Hemlock bearing N 32° W 6 lks. [3.96']). (Book 3, Page 339) – Found 26" dia. Hemlock, (was 18"), (bearing S 76° W 21.3'), healed scar and yellow metal location tag. (Book 3, Page 339) – Found rotten Hemlock Stump, (was 10"), (bearing East) 21.9' (21.3'), scribing visible and yellow tag.					
() Indicates record information, Tillamook County Survey Records. [] Indicates record links converted to feet.					
Monument Set (P N/A	rocedures and l	Description):	Sketch	of F	ound Monument:
376 17 • 16 1/4 CZ. CORP 1970					76 17 € 16 1/4 CZ. CORP
New Accessories		**************************************		ndella della d	
Set 120 lbs. of concrete in a 12" dia. cylinder around monument.					
New Bearing Trees Marked: *13" dia. Hemlock bearing N 78°30' E 44.2', scribed, "T2SR10W1/4S16BT", tagged and painted. *19" dia. Hemlock bearing S 16°30' E 12.6', scribed, "T2SR10W1/4S16BT", tagged and painted. *Indicates an aluminum nail with a washer marked, "Till. Co. Surveyor" set in the face between the scribed "B" and "T" and a yellow metal location tag affixed in an upper blaze. Location & Comments:					
N/A				ŀ	
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 1510 3 rd Street, Suite C Tillamook, Oregon 97141 Party Chief: Joe Jensen, P.L.S. 60067, Deputy County Surveyor					REGISTERED PROFESSIONAL
Notes: Digital images were taken of the monument and its accessories.				-	LAND SURVEYOR
Witnesses: Dann	ny R. McNutt, P.I	aken of the monument and its access. S. 49230, Tillamook County Surve S. 86926, Survey Technician	The state of the s	Amount	Jaseph V. Genser OREGON JANUARY 10, 2008
	THOOK CO				JOSEPH V. JENSEN 69067 RENEWAL DATE: 03-20-2013

JUN 1 2 2013

800K 8 025