OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: Section 21	TOWNSHIP 1 North	RANG	RANGE 10 West			
COUNTY: Tillamook				DATE: 05-10-16		
	Stone A" being The Initial Point of T			(Please check one)		
the Town of Garibaldi, Section 21, Township 1 North, Range 10 West, W.M.			Condition Report Only			
		×	Restoration			
				Rewitness		
				Unrecorded		
			X	Reset at surface		
				Referenced Out		

Previous Rewitnesses, Restorations and Surveys, etc: See maps A-6499, A-5876, A-5051, A-5153, B-237, A-3210, B-889, A-3953, A-3358, A-3357, A-5222, A-5226, A-50, C-230, B-17, Tillamook County Survey Records; See Hays field book "G", PAGE 2, Tillamook County Survey Records for the 1886 reset of "Stone A". See Rewitness Card #47, Tillamook County Corner Rewitness Cards; See Book "C", Pages 142 – 143, Tillamook County Clerks Records.

Found Monument(s) and Accessories (Condition & Source): Stone 'A' was originally set in 1882 and then reset by the County Surveyor in 1886. In 1969, the Tillamook County Surveyor found a 1-1/2" diameter iron pipe in a concrete tile which was held as "Stone A" by John Carlich, L.S. 287 (see Rewitness Card #47). This point was torn out in 2015 by utility construction along the southerly edge of Bay Lane road. The corner accessories listed on Rewitness Card #47 are all missing.

Monument Set (Procedures and Description): The monument was reset using GPS coordinates obtained by GPS observations for work done by the Tillamook County Surveyor's Office on May 05, 2001. The observation is recorded in field book "F", GPS Unit 2545, 3-13-01 to 4-10-03.

We set a 3" diameter Tillamook County Surveyor Brass cap in a cast iron monument box and concrete stamped "T1N R10W STONE A 2016", and as shown hereon.

Coordinate horizontal datum information:

Oregon North Zone, State Plane Coordinates, NAD '83-'91, U.S. Survey Foot.

Northing = 707851.369 Easting = 7326121.866 Picture of Set Monument:



New accessories set: Set a small PK nail at the entrance to an existing concrete ramp. The PK nail bears South 78° West 18.3' from the monument. Set a hat section post with a yellow metal location tag which bears South 5'. The southwest corner of house number 1208 Bay Lane Road which bears North 25° East 39.7'.

New Bearing Trees set: No new bearing trees were set as there are no suitable trees in this area.

Location & Comments: The corner is located approximately 24 feet North of the centerline of the existing railroad tracks and along the southerly edge of Bay Lane Road.

Firm / Agency:

Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE

1510 Third Street, Suite C Tillamook, Oregon 97141

Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor; Deputy County Surveyor.

Notes: Digital images were taken of the set monument.

Witnesses: Michael R. Rice, P.L.S. 86926, Tillamook County Surveyor.
Travis Porter, Survey Technician.

SURVEYOR'S SEAL

REGISTERED PROFESSIONAL LAND SURVEYOR

OPESON JANUARY 10, 2008 JOSEPH V. JENSEN 40067

RENEWAL DATE: 68-30- /7

