## OREGON PUBLIC LAND CORNER REPORT/RESTORATION REPORT **Tillamook County Surveyor's Office**


SECTION:	27 AND 34	TOWNSHIP:	4 SOUTH	RANGE:	10	WEST	
COUNTY:		TILLAMOOK			- 150	DATE:	19-Mar-19
CORNER DESIGNATION:					(Please Check One)		
WEST 1/16 BETWEEN SECTION 27 AND 34					Condition Report Only		
						Restoration	
						Rewitness	
						Not Found	
					X	SET	
						Referenced	Out
Previous Rew	itnesses. Restora	tions, Surveys, etc					

MAP B-2499 SHOWS CALCULATED POSITION, SEE ALSO MAP B-904

Found Monument(s) and Accessories(Condition & Source):

Monument Set(Procedures & Description):

SET 1 1/2" X 30" GALVENIZED IRON PIPE WITH 2 1/2" BRASS CAP STAMPED AS SHOWN, AT CALCULATED POSITION SHOWN ON MAP B-2499.



Other New Accessories Set:

SET STEEL POST WITH LOCATION TAG NORTH 1.0'; SET 5/8" X 30" REBAR WITH PLASTIC CAP MARKED "TERRY JONES LS 2507" 1' EAST OF EAST EDGE PAVING BEARS S 48°36'23" E 169.39'; 5/8" X 30" REBAR WITH PLASTIC CAP MARKED "TERRY JONES LS 2507" BEARS N 89°03'08" W 200.00', SEE MAP B-2499

**New Bearing Trees:** 

NO SUITABLE BEARING TREES IN THE AREA

**Location & Comments:** 

CORNER IS WESTERLY +/- 120' FROM CENTERLINE OF CEDAR CREEK AND JENCK COUNTY ROAD, ON A NORTHEAST FACING SLOPE

Firm/Agency:

**BAYSIDE SURVEYING** 

Address:

11765 HWY 101 SOUTH TILLAMOOK, OR 97141

Party Chief:

TLJ

Office Use Only


Surveyor's Stamp

Notes:

REWITNESS\4S-10-W1-16-S27-S34.XLS

Witness(es):

DWE. DCA



REGISTRA RED **PROFESSIONAL** 

LAND SURVEYOR

JULY 25, 1991

TERRY L JONES

6-30-19

-yours

Leny