

(46)

CHAINS
FEET

Set an iron pipe $1\frac{1}{2}$ inches in diam. 3 ft. long, filled with charcoal, with an Oregon State Board of Forestry bronze cap stamped 1/4 S13, S24 1949, 199

from which:

A fir stump 40 inches in diam. bears S 30° E a distance of 26.2 ft., scribed 1/4 S24, 199

A fir snag 38 inches in diam. bears N 30° E a distance of 53.7 ft., scribed 1/4 S13 199

A metal location poster on a fir snag 48 inches in diam. bears S 65° E a distance of 31 ft.

5266.6 The corner to Secs. 13, 14, 23, 24.

The above work done by Don Davis, transitman, Bruce Thomas and Wayne Frank, chainmen, Douglas Rogers, flagman, under my direction.

Lyle E. Beyers
Forest Engineer

Lyle E. Beyers
Forest Engineer