

CHAINS

8.

Established Corners:

Page (118)

Quarter Section Corner 21/22 T3N, R10W, W.M.


Original:

Post, from which

72" spruce 342°W 23 Lks
5" Hemlock 342°E 40 "

Not Found.

No evidence that this corner has ever been found. Running North from 1/4s 28/27 Topography checks original notes to 21/22 28/27 North of which there is no check with the topography. Probably never set.



Established Corner: By proportion from

16/15 to 21/22
21/22 28/27

set an iron pipe 3/4" x 36" from which,

72" Hemlock 343°47'E 17° ft., scribed 1/4s BT
E

April 7, 1951.

Established Corner: (c4)

Hub of section 21, T3N, R10W, W.M. set at the intersection of the N-S and E.W. 1/4s lines.

A 3/4" x 29" GI Pipe, from which

14" spruce 526°51'E 23 1/2 ft., scribed 1/4s E.
30" Hemlock N45°W 89 " " 1/4s BT.

April 5, 1951