

CHAINS

Relative to the bearing of the random line the true line through the center of Sec. 24 bears N 02°55' W a distance of 5261.0 ft.

2720.3 Point on true line adjustment from temporary stake 2716.8 West 138.1 ft.
Established direction of true line.
S 2°55' E a distance of 90.3 ft.

2630.0 Intersect the true line N 88°29' E through the center of Sec. 24 at a point 20.0 ft. N 88°29' E of the mid point stake 2620.8.

The center of Sec. 24 at point of intersection.

Set an iron pipe 1½ inches in diameter, filled with charcoal, with an Oregon State Board of Forestry bronze cap stamped: C 1/4 S24 1949 199

from which:

A fir snag, 48 inches in diam., bears N 25° W. a distance of 68.0 ft., scribed: BT C 1/4 S24 199.

A location poster on a fir stump 48 inches in diam., bears S 35° E, a distance of 53.6 ft.

Placed a mound of stone around the corner pipe.

Establishment of CS 1/16 Sec. 24.

The true line bet. 1/4 cor. to Sec. 24 & 25 and the center of Sec. 24 bears N 02°55' W, a distance of 2630.0 feet.
Mean = 1315.0

1315.0 Point for CS 1/16 cor. Sec. 24.
Adjustment from temporary stake 1320. Set South 6.8 ft. West 66.8

Set an iron pipe 1½ inches in diam., 3 feet long, filled with charcoal, with an Oregon State Board of Forestry bronze cap stamped: S 1/16 C-C S24 1949, 199.

from which:

A fir snag 58 inches in diam., bears N 35° W a distance of 10.0 ft. scribed: BT S 1/16 S24 199.

A location poster on a fir 48 inches in diam., bears S 47° W a distance of 32.0 ft.

Placed a mound of stone around the corner pipe.