

# TITTLE CONSTRUCTION CO.

2306 10TH STREET

P. O. BOX 229

TILLAMOOK, OREGON

CLAIRE G. TITTLE  
LICENSED CIVIL ENGINEER

PHONE VICTOR 2-2221

March 29, 1960

Mr. W. E. Anderson  
County Surveyor  
Tillamook, Oregon

Dear Bill:

There being no physical evidence of the  $\frac{1}{4}$  corner common to Section 31, Twp. 1 S., Range 9 W. and Section 6, Twp. 2 S., Range 9 W, and there being only one bearing tree existing, I set an  $1\frac{1}{2}$ " iron pipe North 7.0 feet from the existing scribed 8" spruce bearing tree and scribed a 16" maple which bears South  $61^{\circ}$  West 27.0 feet.

Set in March, 1960, in the presence of Ken Tittle

I have established the  $1/16$ th corner which is the southeast corner of the southwest  $\frac{1}{4}$  of the southeast  $\frac{1}{4}$  of Section 24, Twp. 3 N., Range 10 W, in accordance with the following procedure:

From the  $\frac{1}{4}$  corner common to Sections 24 and 25, which is a 1" iron pipe 1.2 feet south of an existing fence, I run South  $89^{\circ}59'$  East 2782.5 feet, where I find a  $\frac{1}{2}$ " iron pipe set by Markham in 1955 for the  $\frac{1}{4}$  corner to Sections 24 and 19. I find his bearing trees (in place with surface scribes plainly visible.

no! (4 section corner)

At South  $89^{\circ}59'$  East 1391.2 feet, I set a 1" iron pipe for the  $1/16$ th corner, from which an 8" alder bears S  $2^{\circ}$  E 11.0 ft.  
9" alder bears N  $75^{\circ}$  W 7.7 ft.  
10" alder bears N  $80^{\circ}$  E 11.4 ft.

Set in March, 1960

In the presence of Dale Mills and  
Tom Dwarte

Very truly yours,

*Claire G. Tittle*

Claire G. Tittle

BOOK 2

411

411