

CHAINS

Page 6. T.3SR10W (cont.)

I found 2"x2" cedar post. ( not the original) Found a 26" splintered hemlock stump, N.75°E., 15 Lks. with visible Mks. "1/4S." Found 16" rotted hemlock stump, N.89°W., 14 Lks. with all marks rotted away.

I set 1" pipe 24" above ground and mark 2 new BTs.

38"fir, S.22°E., 50 Lks., Mkd. 1/4S25BT  
 33"fir, N.35°W., 52Lks., Mkd. 1/4S26BT

Corner is located on a N. slope 40 ft. S. of a ravine running N. 48°E.

Witness: Ed Gory  
 by Leonard Whitmore, Tillamook Co. deputy surveyor. 5-11-62

26 | 25  
 35 | 36

Sec. corner to secs. 25-26-35-36  
 Original Monument  
 10"alder mkd. T.3S525 on N.E., R10WS36 on S.E., S35 on SW., S26 on NW.  
 Original Witnesses:

10" hemlock, N.8°E., 41 Lks. Mkd. T.3SR10WS25BT  
 11" hemlock., N.68°W., 45Lks. Mkd. T.3Sr10Ws26BT  
 14" hemlock., S.34°E., 57 Lks. Mkd. T.3SR10WS36BT  
 20" hemlock., S.27°W., 74 Lks. Mkd. T.3SR10WS35BT

I found 2"x2" hemlock squared post 42" above ground in good condition set by L. Whitmore 1960.

Found 37" sawed off hem stump, S.29°E. (not S.34°E. as orig.) 57 Lks. with visible Mks. "10W." Found 34" hemlock with a chopped open face, N.68°W. 45 Lks. With a visible mark "T". Found 32" sawed off hemlock stump, N.8°E., 41 Lks. with a healed witness face. The SW BT is missing.

BOOK 3

BOOK 3