

See Book 10 P 29 31/32 ZS9

Found 1 Iron Bolt ± 8' Above ground
with 4x4x48" Hem Post ± 6" Ely of
Bolt

Found Both BTS. Both Trees Are
Down & Rotting Can still see Sinking
New BTS.

24" Hem S 34W 20⁶⁵ 1/2 S31 BTCS

20" Hem S 76°30E 13⁰⁰ 1/2 S32 BTCS

12/19/67 Set 2" IP @ Bolt position & Paddle boards
SA SKimmer 5/24/65 on BTS.

G Arthur 10-29

X

NNW Cox H Smith
DLC # 45

Records checked COV & witness field checked 12/67
Found 3" I.P. ± 3" Above Ground & Kaul LCS.

Still in good shape

1-3-68 (Set Hat section 1 1/2 E. of GOS.
ADGM

Found old BT.

24" Hem North 37⁰⁰ BT S DLC CS

18" PB 20" Spt S10W 55⁰⁰ New BT S
7/6

NW DLC # 45 BTCS

PB 16" Spt N60E 17⁵⁰

18" TAG SA SKimmer 5/24/65

G Arthur

See Book 1 Page 4 4-56