

1/16th corner 1 N R 10 W.

Section corner 12 T. 1 N R's. 9 and 10 W. We drove an iron pipe for the corner to this section and scribed the following trees:

- A 32" hemlock S 66° E 11.8' S 18 B.T. Y. tag
A 16" cedar N 43° E 40.7' S 7 B.T.
A 4" hemlock S 65° W 29.7' S 13 B.T.

Scribed by O. R. Miller
Witnessed by E. Erickson, O. B. Jackmond,
W. E. Jordan, 7-31-50

Var. $20^{\circ} 45'$ E.

1/16 corner 4 tallies West of 1/4 corner 12 T. 1 N R 10 W. We established the
13

1/16th corner midway between the 1/4 cor. 12 and the Sec. cor. 11 12 T. 1 N
13 14 13

Range 10 W. and set a 1" toller tube and stake for corner and scribed the following trees:

- A 36" hemlock N 52° W 23.8' (1/16 S 12 B.T.) Yellow tag
A 32" " S 2° W 16.6' (1/16 S 13 B.T.)

Scribed by E. Erickson
Witnessed by O. B. Jackmond, 8-10-50

1/4 corner 13/18 T. 1 N R 9 and 10 W. We established the 1/4 corner 13/18 T. 1 N.,
ranges 9 and 10 W by single proportional measurement, drove an iron pipe and
scribed the following bearing trees:

- 5" hemlock N 83° W 1/4 S 13 B.T. Yellow tag
5" " N 74° E 1/4 S 18 B.T. " "

Scribed by W. L. Robinson
Witnessed by J. G. Rodgers, 9-5-51

N 1/16 corner 13/8 T. 1 N R's. 9 and 10 W. We established the North 1/16th
corner between 13/18, T. 1 N R's 9 and 10 W. by single proportional measurement.
We set an iron pipe from which:

- A 14" hemlock bears S 74° W 17.6', Scribed 1/16 S 13 B.T. Yellow tag
A 14" " " S 52° E 20.5' " 1/16 S 18 B.T. " "

Scribed by W. L. Robinson
Witnessed by J. G. Rodgers, 9-5-51

S 1/16th corner 13/18 T. 1 N R's. 9 and 10 W. We set the S 1/16th sec. corner
between sections 13/18 T. 1 N R's. 9 and 10 W. by single proportional measure-
ment. We drove an iron pipe and scribed the following trees:

- An 11" spruce N 7° E 7.0' 1/16 S 18 B.T. Yellow tag
A 14" spruce N 85° W 19.0' 1/16 S 13 B.T. " "

Scribed by W. L. Robinson
Witnessed by J. G. Rodgers, 9-5-51

1/4 corner 13 T. 1 N R 10 W. We find a 34" spruce scribed "S $\frac{1}{4}$ C.S." supposed to
be the 1/4 corner 13 T. 1 N R 10 W.

E NO08

O. R. Miller, Ed. Erickson, O. B. Jackmond,
W. E. Jordan, July 27, 1950.

Borough of North Range 20 Range

3. Section corner 12 7 T. 1 N R's 9 and 10 W. We drove an iron pipe for the corner between 13 10 and 11 11. We drove an iron pipe for the corner and scribed the following bearing trees:

A 32" hemlock S 66° E 11.8' S 16 D.T. Y. tag
 A 26" cedar N 43° E 40.7' S 7 D.T.
 A 4" hemlock S 65° W 29.7' S 13 D.T.

Scribed by G. R. Miller
 Witnessed by E. Erickson, G. B. Jackson,
 W. L. Jordan, July 21, 1940.

162 10° 45° N.

4. 1/16 corner A 1/16th West of 1/4 corner 12 7 T. 1 N R 10 W. We established the 1/16th corner midway between the 1/4 cor. 13 10 and the Sec. cor. 11 11 T. 1 N ranges 10 W. and cut a 1" boiler tube and stake for corner and scribed the following bearing trees:

A 9" hemlock N 52° W 13.0' (1/16 S 12 D.T.) Yellow tag
 A 32" " S 2° W 14.6' (1/16 S 13 D.T.)

Scribed by E. Erickson
 Witnessed by G. R. Jackson, G. B. Jackson

5. ~~1/4 corner 12 7 T. 1 N R 10 W.~~ We find a 10" rescribed hemlock D.T. for the ~~Section corner~~. We find no stakes or pipe at this corner.

Present: G. R. Miller, E. Erickson,
 W. L. Jordan, G. B. Jackson, July 21, 1940.

6. 1/4 corner 12 7 T. 1 N R 10 W. We find a 34" spruce scribed "S 1/4 NW" supposed to be the 1/4 corner 11 7 T. 1 N R 10 W.

G. R. Miller, E. Erickson, G. B. Jackson,
 W. L. Jordan, July 21, 1940.

7. 1/4 corner 13 10 T. 1 N R 9 and 10 W. We established the 1/4 corner 13 10 T. 1 N., ranges 9 and 10 W by single proportional measurement, drove an iron pipe and scribed the following bearing trees:

5" hemlock N 83° W 1/4 S 13 D.T. Yellow tag
 5" " N 74° W 1/4 S 15 D.T. "

Scribed by W. L. Robinson
 Witnessed by J. G. Ridder, G. B. Jackson

8. W 1/16 corner 13/14 T. 1 N R's 9 and 10 W. We established the North 1/16th corner between 13/14, T. 1 N R's 9 and 10 W. by single proportional measurement. We cut an iron pipe from which:

A 14" hemlock bears S 74° W 17.6' Scribed 1/16 S 13 D.T. Yellow tag
 A 14" " " S 52° E 20.5' " 1/16 S 15 D.T.

Scribed by W. L. Robinson
 Witnessed by J. G. Ridder, G. B. Jackson

Smith 1 North, Range 10 West

Sec. corner 12 18 T. 1 N., R. 10 W and 9 N. After running all north, south
21 19 11 18 east and west lines from Sec. cor. 24 19 T. 1 N., R. 9 and 10 W., I made a
very diligent search for this section corner or evidence of the same and find
a 26" hemlock stub badly decayed. No scribe shows. Not entirely convinced
that this is the original bearing tree for this section corner, I begin at
Section corner 1 6 T. 1 S., R's 9 and 10 W and run north, retracing the
12 7 11 18

range line to verify the evidence at Section corner 24 19 T. 1 N., R's 9 &
10 W. Checking with the original field notes in retracing the range line I
find the creek and ridge ties in accord with those described in the original
field notes. Proceeding north to the approximate position of the section corner
I find the hemlock stub to be on the original range line. The position of this
evidence is further verified by the stream tie to Pine Creek approximately 100
feet north of the position of the corner.

I am firmly convinced that this hemlock stub is the remains of the original
bearing tree marked by the original land surveyor in 1873. I am certain be-
yond any doubt that setting this corner from this evidence will place this
corner in the original position and that a restoration of this corner by any
other method would result in this corner being erroneously set. From this
bearing tree I set a 3" x 3" x 36" cedar post for the corner as per distance
and bearing as recorded in the original field notes. This corner was refferenced
as follows:

8" Hemlock 8' 3" E 90.2 feet Land number 8 19
20" spruce 7' 2" E 50.8 " " " 8 18
32" spruce 7' 3" E 72.2 " " " 8 19

Determined and restored by G. R. Miller of L.P.
McMinnville J. D. Budgett
G. R. Jackson

August 26, 1951

2. 1/4 quarter 12 T. 1 N. R 10 W. We find a 34" spruce marked "8 1/2 C.R." supposed to
be the corner 12 T. 1 N. R 10 W.

G. R. Miller, M. Erickson, G. R. Jackson,
McMinnville, July 27, 1951.

See PAGE 4

8 1906

Township 1 North, Range 10 West

1. 1/4 corner 12 Township 1 North, Range 10 West. Found hemlock
B.T. at 1/4 corner 12. From distance and bearing in original
field notes drove an iron pipe for 1/4 corner. Scribed following trees:

26" Hemlock N 72 deg. E. 18.3' 1/4 S 12 B.T.
24" " 21 " W. 19.6' 1/4 S 13 B.T.

Placed yellow tag at corner.

Scribed by: C. R. Miller, LFCC.
The original B.T. is N 30° W 9 lbs. Witnesses: E. Erickson
O. B. Jackmond

Wm. Jordan

July 25, 1950

2. Sec. corner 12 18 T. 1 N., R. 10 and 9 West. After running all north, south,
24 19 12 18

east and west lines from Sec. corner 24 19 T. 1 N., R. 9 & 10 W., I made a
very diligent search for this section corner or evidence of the same and find
a 20" hemlock stub badly decayed. No scribe shown. Not entirely convinced that
this is the original bearing tree for this section corner, I begin at section
corner 1 6 T. 1 S R 9 and 10 W and run north retracing the range line to
12 7 12 18

verify the evidence at section corner 24 19 T. 1 S R 9 and 10 W. Checking
with the original field notes in retracing the range line I find the creek and
ridge lines in accord with those described in the original field notes. Proceed-
ing north to the approximate position of the section corner I find the hemlock
stub to be on the original range line. The position of this evidence is further
verified by the stream tie to Moose Creek approximately 100 feet north of the
position of the corner. I am firmly convinced that this hemlock stub is the
remainder of the original bearing tree marked by the original land surveyors in
1873. I am certain beyond any doubt that restoring this corner from this
evidence will place this corner in the original position and that a restoration
of this corner by any other method would result in this corner being erroneously
set. From this bearing tree I set a 3" x 3" x 36" cedar post for the corner
as per distance and bearing as recorded in the original field notes. This
corner was referenced as follows:

5" hemlock S 3° E 9.3 feet. Lead washer S 19
30" spruce N 27 E 50.8 " " S 18
32" spruce N 34 E 72.2 " " S 18

Referred and restored by:

Co y Surveyor's Record, Tillamook Co y, Oregon

Section 13, Corner 10 West

1/4 corner 13 T. 1 North, Range 10 West. Found Hemlock B.T. at
13

1/4 corner 13. From distance and bearing in original field notes
drove an iron pipe for 1/4 corner. Scribed following trees:

28" Hemlock N 72 deg. E. 18.8' 1/4 S 12 B.T.
24" " S 21 " W. 19.0' 1/4 S 12 B.T.

Placed yellow tag at corner.

Scribed by O. R. Miller, LFCO.

The orig. B.T. is N 10° W 9 lbs. Witnesses: E. Erickson

O. B. Jackmond

Wm. Jordan

July 25, 1950

3

Sec. corner 13 18 T. 1 N., R. 10 and 9 West. After running all north, south,
24 19 13 18

east and west lines from Sec. corner 24 19 T. 1 N., R. 9 & 10 W., I made a
very diligent search for this section corner or evidence of the same and find
a 20" hemlock stub badly decayed. No scribe shows. Not entirely convinced that
this is the original bearing tree for this section corner, I begin at section
corner 1 6 T. 1 S R 9 and 10 W and run north retracing the range line to
12 7 13 18

verify the evidence at section corner 24 19 T. 1 N R 9 and 10 W. Checking
with the original field notes in retracing the range line I find the creek and
ridge ties in accord with those described in the original field notes. Proceed-
ing north to the approximate position of the section corner I find the hemlock
stub to be on the original range line. The position of this evidence is further
verified by the stream tie to Moss Creek approximately 100 feet north of the
position of the corner. I am firmly convinced that this hemlock stub is the
remains of the original bearing tree marked by the original land surveyors in
1873. I am certain beyond any doubt that restoring this corner from this
evidence will place this corner in the original position and that a restoration
of this corner by any other method would result in this corner being erroneously
set. From this bearing tree I set a 3" x 3" x 36" cedar post for the corner
as per distance and bearing as recorded in the original field notes. This
corner was referenced as follows:

8" hemlock S 3° E 9.3 feet.	Lead washer	S 19
30" spruce N 27 E 50.8	" "	S 18
32" spruce N 34 1/2 W 72.2	" "	S 13

Referenced and restored by:

O. R. Miller of LFCO.

Witnesses:

J. Rodgers

O. B. Jackmond

August 24, 1951

Sec. corner 11 18 T. 1 N R 10 W. We find a 40" rescribed hemlock B.T. for the
section corner. We find no stakes or pipe at this corner.

BOOK 3

Present: O. R. Miller, E. Erickson,
Wm. Jordan, O. B. Jackmond, July 25, 1950

2

3 BOOK 3

BOOK 3

16 -