

County Surveyor's Record, Tillamook County, Oregon

CHAINS

$\frac{1}{4}$ $\frac{2 1/2}{1/2}$ 1510
 Replaced w/ 2" IP flush w/ horizon
 Found 1" IP with Hook on side
 Badley Bent. Straiten Pipe
 & Put Back By Calls
 Put A. 2x4x105 pr post S/W
 Side of P. pipe 4' High.

 W.E. Andersen B.T. Still good?
 22" Horn Now Stamp S7°30' E 21'
 16" Horn " " N77° E 22'
 Cor is in A Log off Area

 S.A. Skinner 5/25/65
 G. Arthur

 See Book 1
 Page 28 57
 Spr Stump N 19° E 33° Y.T. PB
 15' x 12' DBH. S1BTCS
 12/67 JLC SA 4343
 Spr Stump S2BTCS
 8' x 50' N42W PB

 BOOK 5 10/23/70
 C.S.