## County Surveyor's Record, Tillamook County, Oregon

CHAINS	
	Conton Section 66  Sec 31 159
	Found 2" IP = 4"Below Surface
	IN Fence Cor & Fence Running  East & South  New BTS  OSHR/WPn 350+00 N4/11/E640 1
	054 R/w Pm 350+00 N4/9// E 640 0 054 R/w Pm 340+00 549 5/E 360 25 2'18 12 R/w Fence, East 4970
	Manil (2) G. Arthur Seo Map "D-150" Scenag "Pelz Cortill 1A-619 = 27-7
	18 18 L
	bne B.T. with is 10' Alder  S44-45W 449 In very Bad shape
	All other BT.S Game Put A 2"IP in For Cat
	24 Ced. \$86E 72 - 7 523 BT C 5
	P.P 25, 45 N45W 20 5 22 BT CS  SASKINGE 6/1/65 WENTE  G.ANTHULL  LE BOLL 1 DAY 87 GLOWY CITY
	Les Book 1 Part 1 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \

121

B00K