

# County Surveyor's Record, Tillamook County, Oregon

CHAINS

		34	35	1510			
(41)	Sec Cor	3	2	2510			
Found 1 1/4" I.P.T. 6 Above Ground							
8 Two Bearing Trees Both							
Tree Are New Stumps							
	60" Hem Stump	S82E		20 <sup>85</sup>		Scrubbing	Just Usable
	48" Hem Stump	S10E		17 <sup>60</sup>		Scrubbing	Just visible
? All other Bearing Trees gone							
I Made New Bearing Trees							
	12" Hem	S55E		24 <sup>48</sup>	( )	"S2 BTCS"	
	12" Hem	N59E		27 <sup>05</sup>	( )	S35 BTCS	
	24" Hem	S65W		8 <sup>50</sup>	( )	S3 BTCS	
	16" Hem	N31W		12 <sup>25</sup>	( )	"S34 BTCS"	
Cor is ± 31 East of East Edge of							
Crown Rd # 107							
SA Skinner 10-11-65							
G Arthur See Book 1-5							
may B-45							
10/25/70							
G. Arthur CS							
BOOK 5							