Resurvey
NE & Section 12, T6S, R9W, W.M.
July 20, 1982
page 3

State Parks Crew Re-Set:

5/8"x30" iron rod with aluminum cap marked "OREGON STATE PARKS" and a galvanized steel post with a plain white paddle 2.0 feet west of iron rod

 $1967~\rm{BT}-19"$ Fir $\rm{S}43^{O}W$ - 28.5° to center has healed over blaze scar, attached a Parks corner tag

1967 BT - 13" Fir $S30^{\circ}E$ - 58.9 foot; has healed over blaze scar

1967 stone fireplace N820E - 94.0 feet

Corner is located 46 feet east of a creek and 23 feet south of an outhouse

1967 iron rod and post that was in error was removed

Witnessed by: A. Slack

S. Doak

R. Lee

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON JULY 9. 1998 JOHN E HOLLINGSWORTH 691

John E. Hollingsworth State Parks & Recreation Division 525 Trade St. SE Salem, OR 97310

meswatt

Les may 1-4807