

County Surveyor's Record, Tillamook County, Oregon

CHAINS

(178)

$\frac{1}{4}$ Cor 21/22 4510

Look For $\$$ Did Not Find Corner
So I set $\frac{1}{2}$ ^{IP for} Corner From Map
Call out of The County Surver
Office Map A-205. These Calls
Fit All Fence & Road Calls.
Corner Falls Ely of Center
of Road 17° $\$$ ^{very} in $\frac{1}{2}$ old E-W
Fence Line $\$$ 1° Wly of Ely R/w Fence.

New Bearing Tree
8" Turn Oregon Maple Sly one.
N $74^{\circ} \frac{1}{2}$ W 48° Scribed $\frac{1}{4}$ 521 BTCS

SW Cor Garage Foundation. N $40^{\circ} \frac{1}{2}$ E 75°

John L Corlich " 287 f CS
Stanley Skinner 6-6-67