

Corner of Sections 18,19 of Township 4 South, Range 6 West, W.M. and
of Sections 13,24 of Township 4 South, Range 7 West, W.M.

June 6, 1988 -- Reset & Update.

This corner was remonumented by BLM in 1941. They found the original
corner monument, a granite stone, 18 x 12 x 12 ins., firmly set, mkd.
with 3 notches on N. and S. edges.

At the corner they set an iron pipe, 3 ft. long, 2 ins. diam., with a
brass cap appropriately marked for the corner, and deposited the stone
at its base. The following bearing trees were marked:

A fir, 14 ins. diam., bears N 45° 30' E 39 lks. distant (Now of 22 ins.
diameter).

A fir, 24 ins. diam., bears S 59° 15' E 44 lks. distant (Now of 36 ins.
diameter).

A fir, 30 ins. diam., bears S 41° 45' W 31 lks. distant (Now a recently
cut stump, of 45 ins. diameter). This B.T. is on top of a narrow
ridge ascending N 52° W.

A fir, 12 ins. diam., bears N 12° 00' W 54 lks. distant (Now of 20 ins.
diameter).

Recent logging activity removed the corner monument, which was left ly-
ing on the site. We checked and measured from all four of the 1941 B.Ts
and reset the same (BLM) monument back on the corner, 30 inches into
the ground, and noted the update information on the bearing trees as
shown above. No trees remain for a new bearing tree in the southwest
quarter.

Norris Jones, Yamhill County Surveyor
& James Sulak, Assistant

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Norris L. Jones

OREGON
JULY 10, 1984
NORRIS L. JONES
648

BOOK 6-354

BOOK 6-354