

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 2 and 11,  
Township 1 South, Range 8 West, W.M., Tillamook  
County, Oregon.

ORIGINAL

Stone 18" x 12" x 7", now lower part of 4 left, found  
downhill out of place, from which a:

- 6" Hemlock bears N20°W 76 lks.; now 18" stub  
4 ft. high, edges of original face, badly  
burnt and rotted.
- 6" Alder bears S14°E 56 lks.; now 10" stub 6'  
high, lower face burnt out, upper face  
rotted out.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap  
marked "OREGON STATE BOARD OF FORESTRY 1/4 S2 S11  
1954 RE 2311," 34 inches in ground, in mound of  
stone 3' x 2' x 20", and from which a:

- 72" Fir snag bears S2½°E 115.0 ft.; scribed  
1/4 S11 BT.
- 76" Fir stump bears N12°W 193.7 ft.; scribed  
1/4 S2 BT RE 2311.

Oregon State Board of Forestry metal location poster on  
63", 11 ft. Hemlock stub N51°E 10.9 ft.  
4" x 4" x 60" white Cedar post 1.5' SE of pipe.

Dated April 1, 1954.

Restored by Arnold G. Gibson under my direction.  
Arnold G. Gibson, Assistant Engineer.



Present and witnessed by Richard Morris.