

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 13, 14, 23 and 24,
Township 1 South, Range 7 West, W.M., Tillamook
County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 16" Hemlock bears S39 $\frac{1}{2}$ °E 46 lks.; now missing, point falls under log, no trace of tree.
- 5" Hemlock bears N31 $\frac{1}{2}$ °E 39 lks.; now missing, point falls in slide area.
- 22" Fir bears N62°W 33 lks.; now 20" stump, BT scribes visible, rest gone.
- 20" Fir bears S23 $\frac{1}{2}$ °W 48 lks.; now 26" uprooted, scribes 1S R7W S23 BT visible, root hole in place.

RESTORED

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1S R7W S14 S13 S23 S24 1954 RE 2311," 32 inches in ground, in mound of stone 2' x 2' x 6", and from which a:

- 72" Fir stump bears N86°E 28.7 ft.; scribed T1S R7W S13 BT RE 2311.
- 50" Fir stump bears N14°W 53.2 ft.; scribed T1S R7W S14 BT.
- 50" Fir stump bears S49°W 44.2 ft.; scribed T1S R7W S23 BT.
- 66" Fir stump bears S59°E 53.5 ft.; scribed T1S R7W S24 BT.

Oregon State Board of Forestry metal location poster on
72" Fir stump BT.
4" x 4" x 60" white Cedar Post 1.5 ft. SE of pipe.

Dated March 23, 1954.

Restored by Richard Morris under my direction.
Richard Morris, Compassman



Present and witnessed by Robert Cowan, Lloyd Geraths
Alan Ramage