

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One-quarter corner common to Sections 15 and 16, T3N, R7W, W.M., Tillamook County, Oregon.

ORIGINAL

24" Hemlock  $\frac{1}{4}$  on West face, now 32" stump, scribe S visible, from which:

15" Hemlock bears N57°W 36. lks.; now 19" stump, scribes BT visible, upper face cut off when logged.

15" Hemlock bears N57°E 23 lks.; now 15" splintered stub 1 ft. high, bottom old face visible, scribes and face gone.

RESTORED

Set 4"x4"x72" White Cedar post on NW side of corner stump, 18 inches in ground, and from which a:

48" Fir stump bears N13°W 38.1 ft.; scribed  $\frac{1}{4}$  S16 BT RE 2311.

52" Fir stump bears N69°E 33.8 ft.; scribed  $\frac{1}{4}$  S15 BT.

Oregon State Board of Forestry metal location poster on 52" Fir stump BT.

Oregon State Board of Forestry metal location poster on original 15" Hemlock BT.

Oregon State Board of Forestry metal location poster on West side of corner stump.

Set 4"x4"x72" White Cedar post on NW side of corner stump.

Dated November 23, 1954.

Restored by Richard Morris under my direction  
Richard Morris, Engr. Aide



Present and witnessed by Claude Weikel  
Forest Logan  
Lloyd Geraths