RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 5, 4, 8 and 9, Township 1 South, Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

4" Hemlock bears N31°W39 lks.. Now 14" snag Scribe 5 visible, rest of face unexposed.

7 Hemlock bears S760W 18 lks.; Now just roots left.

18" Hemlock bears S51°E 36 lks.; Now roots in place. 24" log down hill out of place, scribes TIS R7 BT visible.

18" Hemlock bears N2120E 207 lks.; Now 30" stub 6' high scribes IS R7W exposed.

RESTORED

Set 12 x 36 galvanized iron pipe with 3 bronze cap marked "OREGON STATE BOARD OF FORESTRY TIS R7W S5 S4 S8 S9 1954 RE 2311," 34 inches in ground, in small mound of stone, and from which a:

> 60" Cedar snag bears N27°E 170.0 ft.; scribed T1S R7W S4 BT. 4" Fir bears N470W 28.0 ft.; scribed X. 59" Fir stump bears S420E 38.2 ft.; scribed T1S R7W S9 BT.

> 72" Fir stump bears S23 W 78.4 ft.; scribed TIS R7W S8 BT RE 2311.

Oregon State Board of Forestry metal location poster on 59" Fir stump BT. 5" x 5" x 60" White cedar post set 1 ft. SW of pipe. Tag on 4" x 4" x 48" White Cedar post 500 ft. N. of Cor on S Edge log Road.

Dated February 25, 1954.

Restored by

under my direction.

Richard Morris, Compassman

Present and witnessed by Lloyd Geraths and Alan Ramage

Book I