

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 15,16,21 and 22,
T1S, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

Stone, 16" x 12" x 7", now missing (corner point falls
in cat road) from which a:

- 24" Hemlock bears N48°W 83 lks.; now 40" snag,
scribes T1S R8W S16 BT visible.
- 5" Spruce bears N39°E 72 lks.; now 27" stub 6'
high, scribes T1S R8W visible, rest unexposed.
- 20" Hemlock bears S29°E 43 lks.; now 44" snag,
scribes T1S R8W S22 BT visible.
- 18" Hemlock bears S55°W 75 lks.; now 41" snag,
bears S65°W scribes T1S R8W S21 visible,
lower face unexposed.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY T1S R8W S16 S15 S21 S22
1955 RE 2311," 33 inches in ground, in mound of stone,
and from which a:

- 6" Hemlock bears N73°E 89.2 ft.; scribed T1S R8W
S15 BT.
- 5" Spruce bears N89°W 83.0 ft.; scribed T1S R8W
S16 BT.
- 5" Spruce bears S68°W 48.4 ft.; scribed T1S R8W
S21 BT RE 2311.
- 5" Spruce bears S39½°E 33.7 ft.; scribed T1S R8W
S22 BT.

Oregon State Board of Forestry metal location poster on 6"
Hemlock BT.

Set 4" x 4" x 60" white Cedar post 1.5 ft. NE of pipe.

Dated February 15, 1955.

Restored by Richard Morris under my direction.
Richard Morris, Engr. Aide



Present and witnessed by Claude Weikel
Forrest Logan
Lloyd Geraths