

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Section 33 (Base line), T. 1N., R. 8W., W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing,

50" Hemlock bears N25°W 7 lks.; now 48" x 7 ft. high stub, scribes $\frac{1}{4}$ visible on burnt face, lower face unexposed.
12" Hemlock bears S18°E 22 lks.; now just roots in place.

RESTORED

Var. $21\frac{1}{2}^{\circ}$

Set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY $\frac{1}{4}$ S33 1955 RE 2311," 34 inches in ground, in mound of stone, and from which a:
46" Fir stump bears N68°W 116.5 ft.; scribed $\frac{1}{4}$ S33 BT RE 2311

Set 4" x 4" x 72" white painted Cedar post 1.5 ft. South of pipe. Oregon State Board of Forestry metal location posted on 46" Fir stump BT.

Also poster on 4" x 4" x 72" white painted Cedar post on East bank log. road 175 ft. East.

Dated August 22, 1955.

Restored by Richard Morris under my direction.
Richard Morris, Engineering Aide



Present and witnessed by Robert Sturm