

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 23, 24, 25 and 26,
T. 3N., R. 7W., W.M., Tillamook County, Oregon.

ORIGINAL

48" Hemlock, now burnt out hollow stub 5 ft. high with only original axe marks remaining, from which a:

12" Hemlock bears N24°E 48 lks.; now 16" uproot, scribes T3N S remaining, root hole in place.

6" Hemlock bears S18°E 50 lks.; now 10" uproot, scribes T3N R6W S25 BT visible, root hole in place.

36" Fir bears N43°W 39 lks.; now 46" stump, portion of scribe visible on upper face, rest unexposed.

10" Hemlock bears S62°W 26 lks. roots remaining.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R7W S23 S24 S25 S26 1955 RE 2311," 33 inches in ground, in mound of stone inside hollow stub, and from which a:

11" Hemlock bears S26½°W 65.0 ft.; scribed T3N R7W S26 BT RE 2311.

50" Fir stump bears N83½°E 60.5 ft.; scribed T3N R7W S24 BT.

47" Fir stump bears S64°E 99.1 ft.; scribed T3N R7W S25 BT.

Set 4"x4"x72" white painted Cedar post 3 ft. NW of pipe. Oregon State Board of Forestry metal location poster on 11" Hemlock BT.

Also poster on 4"x4"x72" white painted Cedar post on South edge road 870 ft. North of corner.

Dated September 19, 1955.

Restored by Richard A. Morris under my direction.
Richard A. Morris, CE I



Present and witnessed by Forrest Logan
Lloyd Geraths
Robert Sturm