

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 7, 12, 13 and 18, T3N, Rgs. 7 & 8 W., W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

52" hemlock bears N19°E 70 lks.; now 56" snag, face & scribes burnt off.

24" hemlock bears S57°E 62 lks.; now 19" stump, scribes & face burnt off.

30" hemlock bears S64°W 47 lks.; now 40" stump, upper face burnt out, scribes visible on partially exposed lower face.

15" hemlock bears N81°W 40 lks.; now 30" stub, 15' high, scribes N R8W SBT visible, rest unexposed, now bears N75°W.

RESTORED

Var. 21½°E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R8W R7W S12 S7 S13 S18 1956 RS 359," 34 inches in ground, and from which a:

35" fir snag bears S89½°E 49.8 ft.; scribed T3N R7W S18 BT.

44" fir stump bears N25°W 62.5 ft.; scribed T3N R8W S12 BT RS 359.

48" fir stump bears S12½°W 54.4 ft.; scribed T3N R8W S13 BT.



38" fir stump bears N62°E 71.8 ft.; scribed T3N R7W S7 BT.

Oregon State Board of Forestry metal location poster on 44" fir stump BT.

Set 4"x4"x72" white painted Cedar post 2 ft. SW of pipe.

Dated July 17, 1956.

Restored by Richard Morris under my direction.
Richard Morris, Transitman



Present and witnessed by Robert Sturm
Lloyd Geraths