

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 25, 26, 35 and 36, T1S, R. 7W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

- 8" Hemlock bears S.20°W. 81 lks.; now missing, point falls in slide area.
- 6" Hemlock bears S.42°E. 28 lks.; roots in place and 8" uproot downhill, scribes S36 visible, rest unexposed.
- 10" Hemlock bears N.48-1/2°E. 30 lks.; now missing, just roots remaining in place.
- 30" Hemlock bears N.18-1/2°W. 33 lks.; now 38" stub 10" high, scribes T1S R7W BT visible, rest burnt off.

RESTORED



Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1S R7W S26 S25 S35 S36, 1956 RS359," 35 inches in ground, in mound of stone, and from which a:

- 6" Fir bears N.34°W. 17.1 ft.; scribed T1S R7W S26 BT RS359.
- 5" Fir bears N.5°E. 12.3 ft.; scribed T1S; R7W S25 BT
- 5" Fir bears S.15 1/2°E. 25.2 ft.; scribed T1S R7W S36 BT.
- 7" Fir bears S.72°W. 110.2 ft.; scribed T1S R7W S35 BT.

Oregon State Board of Forestry, metal location poster on 6" Fir BT.
Set 4 x 4 x 72" white painted cedar post 1.5 ft. SW of pipe.

Dated May 14, 1956

RESTORED BY Richard Morris under my direction.
Richard Morris, Transitman



Present and witnessed by Robert Sturm
Millard Trout