

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 2 and 3,
Township 3 North, Range 8 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing from which a:

- 24" Hemlock bears N62 $\frac{1}{2}$ °E 66 lks.; now 46" stub 10' high,
scribes $\frac{1}{4}$ " S BT visible.
- 4" Hemlock bears S33°W 34 lks.; now missing, point falls
in slide.

RESTORATION by unknown persons, (no record at C.S. office)

Found 3"x3"x30" Fir limb scribed $\frac{1}{4}$ " S3 on NW and 2 on SE
(now in place) from which a:

- 6" Fir bears N36°E 6.8 ft.; scribes $\frac{1}{4}$ " S, now in good
shape.
- 5" Alder bears S21°E 14.6 ft.; scribes $\frac{1}{4}$ " S in bark,
now in good shape.

RESTORED


Set 1 $\frac{1}{2}$ " x36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY $\frac{1}{4}$ " S3 S2 1956 RS 359,"
35 inches in ground with scribed fir limb on N edge,
and from which, a:

- 8" Fir bears N40°E 24.7 ft.; scribed $\frac{1}{4}$ " S2 BT RS 359.
- 6" Fir bears S88°W 40.7 ft.; scribed $\frac{1}{4}$ " S3 BT.

Set 4"x4"x60" white painted Cedar post 1 ft. SW of pipe
Oregon State Board of Forestry metal location poster on 8" fir BT.

Dated June 4, 1956

Restored by Richard A. Morris under my direction.
Richard A. Morris, Transitman



Present and witnessed by L. Geraths
R. Sturm
W. Peterson