CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 8, 9, 16 and 17 T. 1S, R. 7W, W.M., Tillamook County, Oregon

ORIGINAL

Post (now missing) from which a:

8" Barberry bears S37°W 24 lks.; now missing. 5" Vine maple bears N71°W 16 lks.; now missing.

30" Fir bears N11°E 49 lks.; now 37" stump, edges of burnt out face visible.

50" Fir bears S55°E 97 lks.; now 46" stump, scribes R7W visible, rest burnt out.

RESTORED

Var .21½°E

Set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY TIS R7W S8 S9 S17 S16 1957 RS401, 33 inches in ground, and from which a:

4" Fir bears N34°W 32.9 ft.; scribed X BT. 66" Fir stump bears S7720W 31.9 ft.; scribed TIS R7W S17 BT RS401. 48" Fir stump bears N700E 16.2 ft.; scribed T1S R7W S9 BT.

Oregon State Board of Forestry metal location poster on 4" Fir BT. Set 4" x 4" x 60" white painted Cedar post 1.0' NW of pipe.

Dated October 25, 1957

Restored by

REGISTERED OREGON LAND SURVEYOR

Richard A. Morris 401

Present and witnessed by Robert Sturm Harold Russell

Book I