CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section Corner common to Sections 13, 14, 23 and 24, T. 2S, R. 9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing, point falls in old cat road) from which a:

30 Hemlock bears N30° 30 E 54 lks.; now 34" stump, scribes BT visible rest unexposed.

20 Hemlock bears N30° 45 W 40 lks.; now 28 uproot, roots in place,

scribes BT visible, rest unexposed.
7 Hemlock bears S52° 30°E 21 lks.; now missing, point falls in old cat road.

10 Hemlock bears S190 30 W 22 lks.; now 17 uproot, roots in place, fallen on face side.

RESTORED

Var. 21 E

Set 1 x 36 galvanized iron pipe with 3 bronze cap marked "OREGON STATE BOARD OF FORESTRY T2S R9W S14 S13 S23 S24 1958 RS401, 33 inches in ground, and from which a:

7 Hemlock bears N50 E 19.7 ft.; scribed T2S R9W S13 BT.

5 Hemlock bears S27E 10.7 ft.; scribed T2S R9W S24 BT.

48 Hemlock bears S53W 29.6 ft.; scribed T2S R9W S23 BT RS401.

5 Hemlock bears N832W 25.2 ft.; scribed T2S R9W S14 BT.

Oregon State Board of Forestry metal location poster on new 7" Hemlock BT Set 4" x 4" x 60" White painted Cedar post 1' S.W. of pipe.

Dated May 28, 1958

Restored by

REGISTERED OREGON AND SURVEYOR

Richard A. Morris 401

Present and witnessed by Robert Sturm Lloyd Geraths