CHAINS

REESTABLISHED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 5, 6, 31 & 32, T. 3 & 4N, R. 9W, W.M., Clatsop & Tillamook Counties, Oregon.

ORIGINAI

(No evidence of original corner found)

RESTORATION by Manius Buchanan, U. S. Deputy Surveyor, Oct. 17, 1891

(No evidence of restoration found)

REESTABLISHED

Set 12" x 36" galvanized iron pipe with 3" bronze cap marked "CREGON STATE BOARD OF FORESTRY T3N T4N R9W S5 S6 S31 S32 1958 RE2311," 28 inches in ground, in mound of stone, and from which a:

14" Alder bears S44°W 17.7 ft.; scribed in bark T3N R9W S6 BT RE2311. 18" Alder bears N51°E 43.9 ft.; scribed in bark T4N R9W S32 BT.

Oregon State Board of Forestry metal location poster on 18" Alder BT. Also poster on white painted 4" x 4" x 72" Cedar post S89° 30'E 25 ft. Midstream N. Nehalem River N89° 30'W 95.0 ft.

Dated June 19, 1958

Reestablished by ______

under my direction.

Rob't. W. Ross, Transitman

Present and witnessed by W. E. Green J. F. Martin

Book I

337

337