

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 4, 5, 32 & 33,
T. 3 & 4N, R. 9W, W.M., Clatsop & Tillamook
Counties, Oregon.

ORIGINAL

Post, (now missing) from which a:

- 24" Hemlock bears S15°W 33 lks.; now missing.
- 12" Hemlock bears S18°E 80 lks.; now missing.
- 15" Hemlock bears N25°W 76 lks.; now missing.
- 15" Hemlock bears N30°E 57 lks.; now 45", scribes R9S visible, also more recent scribes T3N R9W S33 visible.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T4N R9W T3N S32 S33 S5 S4 1958 RE2311," 28 inches in ground, and from which a:

- 19" Hemlock bears N15°E 32.9 ft.; scribed T4N R9W S33 BT.
- 14" Spruce bears N78°15'W 26.3 ft.; scribed T4N R9W S32 BT.
- 18" Hemlock bears S76°30'E 33.7 ft.; scribed T3N R9W S4 BT.
- 22" Spruce bears S27°30'W 21.2 ft.; scribed T3N R9W S5 BT RE2311.

Oregon State Board of Forestry metal location poster on 18" Hemlock BT.
Another poster on white 4" x 4" x 6' Cedar post 1.0 ft. NW of pipe.

Dated May 28, 1958

Restored by *R. W. Ross* under my direction.
R. W. Ross, Transitman



Present and witnessed by J. F. Martin
J. E. Wilson
Wm. Bonsanti

Book I