**CHAINS** 

REESTABLISHED CORNERS FOR OREGON STATE BOARD OF FORESTRY (See official plat)

Section corner common to Sections 12 and 13 (East side), T1S, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

(No evidence of original corner found)

REESTABLISHED

Var. 212E

Set 12" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY TIS R8W R7W S12 S18 S13 1958 RS401", 35 inches in ground, in mound of stone, and from which a:

60" Fir stump bears S35½W 216.2 ft.; scribed T1S R8W S13 BT RS401. 6" Fir bears N30 3/4W 86.1 ft.; scribed X BT.

Oregon State Board of Forestry metal location poster on 6" Fir BT. Set 4" x 4" x 72" white painted Cedar post 1.5' E. of pipe.

One Quarter corner for Section 13 (East side), TlS, R8W, W.M., Tillamook County, Oregon.

ORIGINAI

(No evidence of original corner found)

REESTABLISHED

Var. 212E

Set 12" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S13 1958 RS401", 35 inches in ground, and from which a:

43" Fir stump bears N 142 W 134.7 ft.; scribed 1/4 S13 BT RS401.

Oregon State Board of Forestry metal location poster on 43" Fir stump BT. Set 4" x 4" x 60" white painted Cedar post 1.4" N.W. of pipe.

Dated December 17, 1958.

Reestablished by

REGISTERED
OREGON
LAND SURVEYOR

Richard A. Morris

Present and witnessed by R. Schulson

H. Russell

R. Cop

Book I

389

359