

CHAINS

ESTABLISHED CORNER FOR OREGON STATE BOARD OF FORESTRY  
(See official plat)

South One Sixteenth corner common to Sections 28 & 29, T2S, R9W, W.M., Tillamook County, Oregon.

ESTABLISHED

Set 1" x 30" iron pipe 6 inches under ground, 13.7 ft. West of Highway center line, and from which a:

27" Cedar bears S72W 43.1 ft.; scribed S 1/16 S29 BT RS401.

3" bronze disc in N end of culvert curb bears S3 1/2 W 130.7 ft.; marked Bench Mark VX43.

Oregon State Board of Forestry metal location poster on power pole N82 1/2 W 15.2 Ft.

REESTABLISHED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 21 and 28, T2S, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

(No evidence of original corner found)

REESTABLISHED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S21 S28 1959 RS401", 33 inches in ground, and from which a:

8" Hemlock bears N62 1/2 W 98.3 ft.; scribed 1/4 S21 BT.

12" Hemlock bears S11 1/2 E 69.9 ft.; scribed 1/4 S28 BT RS401.


Oregon State Board of Forestry metal location poster on 8" Hemlock BT.

Set 4" x 4" x 56" white painted Cedar post 1.0' S.W. of pipe.


Corner located on E. edge of power line clearing.

Dated April 14, 1959

Reestablished by



*Richard A. Morris*



Present and witnessed by H. Russell  
R. Cop