

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 14 and 23 (West end), T2S, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing, point falls in old road course NE & SW) from which a:

12" Hemlock bears S65E 18 lks.; now 13" stump, outline of lower face visible, scribes rotted off, found scribes T2S R9W on log removed from stump.

15" Hemlock bears N69E 23 lks.; now broken up uproot, roots in place, bottom of rotted out face visible.

RESTORED

Var. 21°30'E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2S R9W S22 S14 S23 1959 RS401", 42 inches in ground, and from which a:

17" Hemlock bears S77E 26.3 ft.; scribed T2S R9W S23 BT.

47" Spruce bears N20E 28.5 ft.; scribed T2S R9W S14 BT RS401.


Oregon State Board of Forestry metal location poster on 47" Spruce BT.
Set 4" x 4" x 50" white painted Cedar post 2.0 feet W. of pipe.

Dated February 19, 1959

Restored by



Richard A. Morris



Present and witnessed by Harold Russell
Robert Cop