

1/4 CS
S BDRY
19-2. S 8.

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One-quarter corner common to Sections 19 and 30, T.2S,
R.8W, W.M., Tillamook County, Oregon.

ORIGINAL

Stone 14" x 9" x 8" (now missing, point falls in slide area) from which a:

5" Spruce bears S18°E 40 lks.; now 36" stump, scribes $\frac{1}{4}$ " S BT exposed.
12" Hemlock bears N41°W 78 lks.; now missing, slide area.

RESTORED

Var. 21 $\frac{1}{2}$ E

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON
STATE BOARD OF FORESTRY $\frac{1}{4}$ " S19 S30 1962 RS 401", 32 inches in ground,
in mound of Stone, and from which a:

50" Cedar bears S89 $\frac{1}{2}$ W 12.2 ft.; scribed $\frac{1}{4}$ " S30 BT RS401.
38" Hemlock bears North 52.0 ft.; scribed $\frac{1}{4}$ " S19 BT.

Set 4" x 4" x 56" white painted Cedar post 1.0 ft. SW of corner pipe.
Oregon State Forestry Department metal location poster on 50" Cedar BT.

Dated February 15, 1963

Restored by Billy E. Davis under my direction.
Billy E. Davis, Transitman



Present and witnessed by A. Duncan
D. Fletcher

