

(1)

CHAINS

SURVEY FOR THE OREGON STATE BOARD OF FORESTRY

February 20, 1951

Var. 18° E.

Restoration of the $\frac{1}{4}$ corner between sections 3 & 34, Township 1 & 2 North, Range 7 West, W.M., Tillamook County, Oregon.

Point for the corner determined by the remains of the original bearing trees and stone.

A hemlock stub, 22 inches in diam., bears N 23° E, a distance of 25.1 ft. (38 lks), scribe marks BT' exposed.

A hemlock stumb (badly burnt and rotted), 48 inches in diam., bears S 28° E, a distance of 55.9 (85 lks), original notes call for a distance of 54.9 feet (83 lks).

A stone 12 X 10 X 10 inches chiseled # on North side.

The point for corner falls on the north edge of stone.

At the point for corner:

Set a $1\frac{1}{2}$ inch iron pipe, 3 feet long, with an Oregon State Board of Forestry bronze cap stamped: $\frac{1}{4}$ S34 S3 1951 199.

from which:

A cedar snag, 44 inches in diam., bears N 64° W, a distance of 71.5 feet, scribed: $\frac{1}{4}$ S BT 199.

A fir stub, 29 inches in diam., bears S 61° W, a distance of 43.5 feet, scribed: $\frac{1}{4}$ S BT 199.

Placed a metal location poster on fir stub leaning over corner and marked it: Sec 34 T2N R7W $\frac{1}{4}$ Cor here below.

The above work done by Don Davis, Transitman; Adolf Berglund & Richard Morris, Chainmen; under my direction.

Lyle E. Beyers
Forest Engineer

