

(2)

CHAINS

SURVEY FOR THE OREGON STATE BOARD OF FORESTRY

February 22, 1951

Var. 22° E.

Restoration of the corner to sections 25, 26, 35 & 36, Township 2 North, Range 7 West, W.M., Tillamook County, Oregon.

Point for corner determined from the remains of the original BT's.

A cedar snag, 17 inches in diam., bears N 37° E, a distance of 11.9 feet (18 lks), exposed parts of scribe marks along edge of burnt out face.

A cedar snag, 24 inches in diam., bears S 51° W, 44.9 feet (68 lks), two old burnt out faces remaining, one above the other.

No evidence of corner stone or other BT's.

Point for corner falls on the edge of cliff.

A witness corner:

At a point bearing N 30° E, a distance of 13.0 feet between the roots on the north side of the 17 inch cedar BT.


Set a 1½ inch iron pipe, 3 feet long, with an Oregon State Board of Forestry bronze cap stamped: W C 13 Ft S 30° W, T2N R7W S26 S25 S35 S36 1951 199.

from which:

A cedar, 13 inches in diam., bears S 81° W, a distance of 26.8 feet, scribed: S 26 199 BT.

A cedar, 38 inches in diam., bears N 10° W, a distance of 16.0 feet, scribed: T2N R7W S25 199 BT.

The above work done by Don Davis, Transitman; Richard Morris and Adolf Berglund, Chainmen; under my direction.



Lyle E. Beyers  
Forest Engineer