

(6)

CHAINS

SURVEY FOR THE OREGON STATE BOARD OF FORESTRY

February 22, 1951

Var. 17° E.

Restoration of the $\frac{1}{4}$ corner to sections 25 & 36, Township 2 North, Range 7 West, W.M., Tillamook County, Oregon.

The point for corner determined by the remains of the original B.T.s.

A fir snag, 38 inches in diam., bears N 01° W, 13.9 feet (21 lks), scribe marks BT' exposed below an old burnt out face.

A hemlock snag, 15 inches in diam., bears S 18° E, 16.5 ft. (25 lks), exposed scribe marks BT' below on old burnt out face.

At the point for corner:

Set a $1\frac{1}{2}$ inch iron pipe, 3 feet long, with an Oregon State Board of Forestry bronze cap stamped: $\frac{1}{4}$ S25 S36 1951 199.

from which:

A fir snag, 48 inches in diam., bears S 04° W, a distance of 26.0 feet, scribed: $\frac{1}{4}$ S BT' 199.

A fir snag, 34 inches in diam., bears N 40° E, a distance of 24.2 feet, scribed: $\frac{1}{4}$ S BT' 199.

Placed a metal location poster on the 38 inch fir BT' & marked it: Sec 24 T2N R7W $\frac{1}{4}$ Cor 10.9 ft. S 01° E.

Filed a mound of stone around corner.

The above work done by Don Davis, Transitman; Richard Morris and Adolf Berglund, Chainmen; under my direction.

Lyle E. Beyers
Forest Engineer

