

CHAINS

SURVEY FOR THE OREGON STATE BOARD OF FORESTRY

January 15, 1951

Restoration of the corner to Sections 20, 21, 28, & 29, Township 2 North, Range 6 West, Tillamook County, Oregon.

Var. 22° E.

The point for corner determined by the remains of the original bearing trees:

A fir stump, 36 inches in diam., bears S 45° E, a distance of 21.8 feet (33 lks.), scribe marks: T2 R6W 28 exposed.

A noble fir snag, 18 inches in diam., bears S 41° W, a distance of 9.2 feet (14 lks.), scribe marks: 2 R6 exposed.

A fir stump, 27 inches in diam., bears N 30° W, a distance of 13.2 feet (20 lks.), no evidence of scribing found.

A hemlock stub, crushed under log, bears N 24° E, a distance of 31.0 feet (47 lks.).

At the corner point:

Set a 1½ inch iron pipe, 3 feet long, filled with charcoal with an Oregon State Board of Forestry bronze cap stamped: T2N R6W S20 S21 S29 S28 1951 199.



From which

A fir tree, 4 inches in diam., bears N 70° E, a distance of 15.5 feet, scribed: S21 BT.

A noble fir tree, 3 inches in diam., bears S 66° W, a distance of 26.5 feet, scribed: S29 199.

Placed a metal location poster on a 4 inch fir tree and marked it: Sec 28 T2N R6W Sec Cor 8.3 ft. N 78° W.

The above work done by Don Davis, transitman; Richard Morris and Bill Kleeman, Chainmen; John McWade, Flagman; under my direction.



Lyle E. Beyers
Forest Engineer