

(17)

CHAINS

SURVEY FOR THE OREGON STATE BOARD OF FORESTRY

January 11, 1951

Restoration of the $\frac{1}{4}$ corner to Sections 16 & 17, Township 2 North, Range 6 West, W.M., Tillamook & Washington Counties, Oregon.

Var. 20° E.

The point for corner determined by a 12 X 8 X 5 inch stone in place and marked $\frac{1}{4}$.

From which:

A fir stump, 46 inches in diam., bears $N 50^{\circ} E$, a distance of 15.2 feet (23 lks.) the overgrowth was not removed but scribing could be distinguished by springing overgrowth from face.

A fir stump, 43 inches in diam., bears $S 80^{\circ} W$, a distance of 10.6 feet (16 lks.) scribe mark S exposed. (The original notes call for the bearing to be $S 80^{\circ} E$).

At the south edge of the 12 X 8 X 5 inch $\frac{1}{4}$ stone:

Set a $1\frac{1}{2}$ inch iron pipe, 3 feet long, with an Oregon State Board of Forestry bronze cap stamped: $\frac{1}{4}$ S17 S16 1951 199.



From which:

A fir stump, 42 inches in diam., bears $N 76^{\circ} W$, a distance of 18.4 feet, scribed: $\frac{1}{4}$ S17 199 Bl.

A hemlock tree, 7 inches in diam., bears $N 42^{\circ} 30' E$, a distance of 29.2 feet, scribed: $\frac{1}{4}$ S16 199.

Placed a metal location poster on the 46 inch fir stump and marked it: Sec 16 T2N R6W $\frac{1}{4}$ Cor. 13.0 ft. S $50^{\circ} W$.

The above work done by Don Davis, Transitman; Richard Morris and Bill Kleeman, Chainmen; and John McWade, Flagman; under my direction.



Lyle E. Beyers
Forest Engineer