

CHAINS

SURVEY FOR THE OREGON STATE BOARD OF FORESTRY

January 11, 1951

Restoration of the section corner to Sections 16, 17, 20 & 21, Township 2 North, Range 6 West, W.M., Tillamook & Washington Counties, Oregon.

The point for the corner determined by the remains of the original bearing trees:

A fir stump, 14 inches in diam., bears N 40° E, a distance of 25.1 feet (33 lks)., small part of scribing showing. Did not expose rest of face.

A fir stump, 26 inches in diam., bears N 60° W, a distance of 24.4 feet (37 lks). Exposed scribe marks: T2N.

A double hemlock snag, 26 inches in diam., bears S 40° E, a distance of 26.4 feet (40 lks)., the old face grown over, did not expose.

A hemlock stump, 36 inches in diam., bears S 44° W, a distance of 10 X 6 feet (16 lks)., parts of scribe marks & scribe mark N visable on the edge of burnt face.

At the corner point:



Set a 1½ inch iron pipe, 3 feet long, filled with charcoal, with an Oregon State Board of Forestry bronze cap stamped: T2N R6W S16 S17 S20 S21 1951 199.

From which:

A fir stump, 40 inches in diam., bears S 74° W, a distance of 35.5 feet.

Placed a metal location poster on the 26 inch fir stump bearing tree and marked it: Sec. 17 T2N R6W Sec. Cor. 25.1 ft., S 60° E.

The above work done by Don Davis, Transitman; Richard Morris and Bill Kleeman, Chainmen; John McWade, Flagman; under my direction.



Lyle E. Beyers  
Forest Engineer