

CHAINS

RESTORED CORNER FOR THE OREGON STATE BOARD OF FORESTRY

November 14, 1951

The corner to sections 4, 5, 8, 9, Township 2 South, Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:
 12" Hemlock bears S80E 19 lks; now missing.
 12" Hemlock bears N 24E 54 lks; now missing.
 8" Hemlock bears S58W 25 lks; now missing.
 20" Fir bears N85W 36 lks; now a 28" fir stump, badly burnt; scribe marks were visible when I was at this corner in 1949, since burnt out.

RESTORED CORNER & BEARING TREES

At the point for corner

Set a 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2S R7W S5 S4 S8 S9 1951 142" 2 1/2 ft. in ground, from which a:


- 48" Fir stump bears N01W 38 lks; scribed T2S R7W S5 BT 142.
 - 46" Fir stump bears S61E 41 lks; scribed T2S R7W S9 BT 142.
 - 58" Fir stump bears S51°30' W 105 lks; scribed T2S R7W S8 BT 142.
 - 65" Fir snag bears N54°30' E 83 lks; scribed T2S R7W S4 BT 142.
- (Distances measured from center of bearing trees).

Nailed a metal location poster on the original 28" fir stump & marked it: Sec 5 T2S R7W Sec Cor 34 lks S85E.



Restored by

Walter M. Robertson



Walter M. Robertson

Present & Witnessed by

Don Davis
Don Davis Asst. Forest Engineer OSBF

Present & Witnessed by

Richard Morris
Richard Morris Chairman OSBF