

CHAINS

RESTORED CORNER FOR THE OREGON STATE BOARD OF FORESTRY

November 13, 1951

The corner common to sections 17, 18, 19, 20, Township 2 South, Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

- 10" Barberry bears N17E 29 lks; now missing.
- 6" V. maple bears N65 $\frac{1}{2}$ W 65 lks; now missing.
- 22" Hemlock bears S23 $\frac{1}{2}$ E 36 lks; now missing.
- 28" Hemlock bears S66 $\frac{3}{4}$ W 27 lks; now a 30" stub, down & badly burnt, the stump hole of which bears S66 $\frac{3}{4}$ W 27 lks; scribe marks visable when I was at this corner in 1950, since destroyed by fire.

RESTORED CORNER & BEARING TREES

At the point for corner


Set a 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked: "OREGON STATE BOARD OF FORESTRY T2S R7W S18 S17 S19 S20 1951 142" 2 $\frac{1}{8}$ ft. in ground. Raised mound of rock around it, from which a:

- 72" Fir stump bears S54E 139.0 ft.; scribed T2S R7W S20 BT 142.
- 89" Fir snag bears N68E 79.5 ft.; scribed T2S R7W S17 BT 142.

No other trees available for scribing.

(Distances measured from the center of bearing trees).

Nailed a metal location poster on the 89" Fir snag BT & marked it: S17 T2S R7W Sec Cor 75.5 ft. S68W.



Restored by

Walter M. Robertson
JAN. 1, 1945
WALTER M. ROBERTSON
142

Walter M. Robertson

Present & Witnessed by

Don Davis Jr.
Don Davis Asst. Forest Engineer OSBF

Present & Witnessed by

Richard Morris
Richard Morris Chairman OSBF