

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Quarter corner common to sections 10 and 15, T. 2 S., R. 7 W.,
W. M., Tillamook County, Oregon.

ORIGINAL

Post; now missing from which a:

- 10" Hemlock bears S11W 47 lks; now 16" stub bears N11W 31.0 ft., faces exposed and badly burnt.
- 10" Hemlock bears N69E 29 lks; now 16" down log, the roots of which we found 10 ft. east attached to a 5 ft. fir stump; exposed scribe marks 1/4 S BT.

RESTORED CORNER AND BEARING TREES


Set a 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY S10 S15 1/4S 1951 2311", 2 1/2 ft. in ground. Raised mound of stone around pipe from which a:

- 60" Fir stump, 20 ft. high with spring board holes to top, bears S30E 15.5 ft; scribed 1/4 S15 2311 BT.
- 50" Fir stump, 4 ft. high, bears N32E 38.5 ft. directly under telephone lines; scribed 1/4 S10 BT.

Placed an Oregon State Board of Forestry metal location poster on 60" Fir stump BT and marked it: Sec 15 T2S R7W 1/4 Cor 15.5 ft. N31°30'E.

Dated December 31, 1951.

This corner was restored by Arnold G. Gibson,
Arnold G. Gibson Assistant Engineer
under my direction.



Present and witnessed by Don D. Davis
Don D. Davis Assistant Forest Engineer