

(105)

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Quarter corner common to section 7, T. 1 N., R. 6 W., W.M., Tillamook County, Oregon

ORIGINAL

Post; now missing, from which a:

36" Hemlock bears S52E 35 lks; now a 36" stub, no evidence of marks found.

30" Hemlock bears S80W 21 lks; now a 32" stub, scribe marks BT exposed.

RESTORED CORNER AND BEARING TREES

Set a 1½" x 36" galvanized iron pipe with 3" bronze cap stamped "OREGON STATE BOARD OF FORESTRY 1/4 S7 1949 199", 2½ ft. in ground, from which a:


12" Fir stub bears S28E 24.3 ft; scribed 1/4 S7 199 BT.

Placed an Oregon State Board of Forestry metal location poster on 36" Hemlock stub and marked it: Sec 7 T1N R6W 1/4 Cor 23.1 ft. N62W.

Dated May 30, 1951.

This corner was restored by _____
under my direction.

Don D. Davis
Don D. Davis Asst. Forest Engineer



Present and witnessed by _____

Richard A. Morris
Richard A. Morris Compassman

Present and witnessed by _____

Douglas Stafford Chainman